



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 10/12/04 Operator CDX API # 3803908166
Property Name La Ar Trion 151-1 Location: Unit N Section 10 Township 24N Range 5W
(Well Name and Number)
Pressure (Shut-in or Producing) _____ Tubing 150 Intermediate _____ Casing 255 Bradenhead 40

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	151m	250				Steady Flow	
10 minutes	151m	250				Surges	Breathed
15 minutes	151m	250				Down to Nothing	
20 minutes	151m	250				No Flow	
25 minutes	151m	250				Gas	✓
30 minutes	151m	250				Gas and Water	
5 minute SI	151m	250				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

REMARKS:

Blew down in 4 mins - surged but no fluid came up



Witness _____

(Position)

NMOCD Test Area: C