

AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-28-04 Operator C.D.X. Rio, LLC API # 3003920604

Property Name Jic. AP Tribal 151 #5 Location: Unit K Section 9 Township 26 Range 15
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 160 # Intermediate 0 # Casing 180 # Bradenhead 0 #

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>						
10 minutes							
15 minutes							
20 minutes							
25 minutes							
30 minutes							
5 minute St							


Steady Flow		
Surges		
Down to Nothing		
No Flow	<u>X</u>	<u>X</u>
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 # Intermediate 0 #

REMARKS:



Witness

Carroll Green T.P.S.

Harry Whitson

Tech T.P.S.

(Position)

NMOCD Test Area: