



NEW MEXICO DEPARTMENT OF ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

Oil CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-30-04 Operator CDX Rio, LLC API # 3003921640

Property Name JICARILLA C-8A Location: Unit B Section 13 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 56 Intermediate _____ Casing 86 Bradenhead 26

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes						Steady Flow	
10 minutes						Surges	
15 minutes						Down to Nothing <u>90 Sec.</u>	
20 minutes						No Flow	
25 minutes						Gas	
30 minutes						Gas and Water <u>X</u>	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead ⊖ Intermediate _____

REMARKS:

v James Simpson
T.P.S. Tech
(Position)

Witness

Harry Whitson T.P.S.

NMOCD Test Area:

