

NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 10/8/04 Operator CDX Gas API # 3003923162
Property Name Jicarilla 151-3E Location: Unit Section 4 Township 26N Range 5W
(Well Name and Number)
Pressure (Shut-in or Producing) Tubing 115 Intermediate 110 Casing 184 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	0	196			196		
10 minutes		198			198		
15 minutes		200			200	X	X
20 minutes							
25 minutes							
30 minutes							
5 minute SI	0			0.5 psi		X	X


Steady Flow		
Surges		
Down to Nothing	X	X
No Flow		
Gas	X	X
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

REMARKS:

Bradenhead blew down in 5 seconds
Intermediate blew down in 5 mins



Duane Harrison CDX
Field Tech

(Position)

Witness