



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

RCVD AUG 7 '12

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV.

DIST. 3

Date of Test 8-7-12 Operator Lizac DEG API #30-0 45-20881

Property Name Sangre de Cristo Well No. 2 Location: Unit 1 Section 34 Township 30 Range 61

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 0 Bradenhead 3.1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>0</u>		
10 min	<u>0</u>		<u>0</u>		
15 min	<u>0</u>		<u>0</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>/</u>	
Surges		
Down to Nothing		
Nothing		
Gas	<u>/</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.2 INTERMEDIATE N/A

REMARKS: BH blew lighter blow - 5 - lighter at 11 min. 15 min.
No H₂S

By [Signature]

Witness [Signature]

(Position)

E-mail address _____