



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX. (505) 334-6170  
[http://nemnr.state.nm.us/ocd/District III/3district.htm](http://nemnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 4-8-10 Operator Four Star Oil & Gas API #30-0 39-05706

Property Name JICARILLA B Well No. 4 Location: Unit M Section 32 Township 25N Range 05W

Well Status (Shut-In) Tubing 860 Intermediate 0 Casing 860 Bradenhead ≤1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>860</u>		
10 min	<u>0</u>		<u>860</u>		
15 min	<u>0</u>		<u>860</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>XX</u>
Nothing	
Gas	<u>XX</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

Oil Cons. Div  
District III

JUL 20 2012

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS: Puff of gas from Bradenhead valve.

By Bruce Martin  
by April E Pohl  
(Position)

Witness \_\_\_\_\_

E-mail address \_\_\_\_\_