



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/oilcons/DistrictIII/district.htm>
Oil Cons. Div
District III

AUG 23 2012

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/17/2012 Operator Backhaus GR API #30-0 39-28765

Property Name JIC 464-29 Well No. 9 Location: Unit Section 29 Township 30N Range 3W

Well Status (Shut-In or Producing) Initial PSI: Tubing 109 Intermediate Casing 74 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		74		
10 min	0		74		
15 min	0		74		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE

REMARKS:

Nothing through out Test

By Robert Talamante Witness
lease operator
(Position)

E-mail address