



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 6-10-2009 Operator Four Star Oil & Gas API #30-0 45-29117

Property Name Riggs Well No. 1 Location: Unit A Section 4 Township 29N Range 12W

Well Status(~~Shut-In~~ or Producing) Tubing 6 Intermediate N/A Casing 5 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		5		
10 min	0		6		
15 min	0		6		
20 min	0		5		
25 min	0		5		
30 min	0		6		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>XX</u>
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

Oil Cons. Div
District III

JUL 20 2012

REMARKS: Puff of gas on Bradenhead valve, blew down to zero in < 1 second.

By Bruce Martin
by Spil E Pohl
(Position)

Witness _____