



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-30-15 Operator Burlington API #30-0 39-25465

Property Name J:1/Santa Fe SW Well No. 1 Location: Unit 1080 Chert Section 8 Township 24 Range 3

Well Status (Shut-In or Producing) Initial PSI: Tubing 940 Intermediate N/A Casing 4:1 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		3.9		
10 min	0		3.8		
15 min	0		3.8		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	/
Nothing	
Gas	/
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Puff when opened.

By David H. Aguirre
SWD mso
(Position)

Witness Monica Kuchling
Research for BH & Intermediate

E-mail address david.h.aguirre@conocoPhillips.com