



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD SEP 5 '12
OIL CONS. DIV.
DIST. 3

Date of Test 9/05/2012 Operator Burlington API #30-0 45-08615
Property Name Cornell Well No. 6 Location: Unit Section 11 Township 29 Range 12
Well Status (Shut-In) or Producing Initial PSI: Tubing 53 Intermediate 0.5 Casing 56.5 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0.5	56.6	0	56.6
10 min	0	0.5	56.6	0	56.6
15 min	0	0.1	56.6	0	56.6
20 min	5	5	5	5	5
25 min	7	7	7	7	7
30 min	7	7	7	7	7

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		X
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0.1

REMARKS:

H₂S investigation. BH slight puff. Gauge on Intermediate powered off before 15 min.
Intermediate had slight puff after 5 min shut in. Nothing on dreg
tube on BH + intermediate

By J. Nelson
m.s.o.
(Position)

Witness Jonathan Kelly

E-mail address