



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distr.htm](http://emnr.state.nm.us/ocd/District%20III/3distr.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 8/2/2010 Operator Chevron Midcontinent, L.P. API #30-0 39-06831

Property Name RINCON UNIT Well No. 130 Location: Unit A Section 32 Township 27N Range 06W

Well Status (Producing) Tubing 73 Intermediate 12 Casing 148 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	0	0	148	0	148
10 min	0	0	148	0	148
15 min	0	0	148	0	148
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	XX
Nothing	XX
Gas	XX
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: The intermediate valve blew down to nothing in 10 seconds.

By Bruce Martin
by April E. Pohl
(Position)

Witness _____

E-mail address _____

Oil Cons. Div
District III

JUL 20 2012