



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 9/28/2010 Operator Chevron Midcontinent, L.P. API #30-0 39-21719

Property Name RINCON UNIT Well No. 83A Location: Unit P Section 23 Township 27N Range 06W

Well Status (Producing) Tubing 50 Intermediate N/A Casing 54 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
5 min	<u><1</u>		<u>54</u>		
10 min	<u>0</u>		<u>54</u>		
15 min	<u>0</u>		<u>54</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>XX</u>	
Nothing	
Gas <u>XX</u>	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

Oil Cons. Div
District III

JUL 20 2012

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS: The Bradenhead line blew down to nothing in ~ 8 minutes.

By Bruce Martin
by April E. Pohl
(Position)

Witness _____

E-mail address _____