



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

✓
BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 8/26/2010 Operator Chevron Midcontinent, L.P. API #30-0 39-24800

Property Name RINCON UNIT Well No. 259 Location: Unit H Section 29 Township 27N Range 06W

Well Status (Producing) Tubing 32 Intermediate N/A Casing 32 Bradenhead vacuum

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>32</u>		
10 min	<u>0</u>		<u>32</u>		
15 min	<u>0</u>		<u>32</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS		
	BRADENHEAD	INTERMEDIATE
Vacuum	<u>XX</u>	
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: The Bradenhead line was on a slight vacuum.

By Bruce Martin
by April E. Pohl
(Position)

Witness

E-mail address

Oil Cons. Div
District III

JUL 20 2012