



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 4-26-10 Operator Four Star Oil & Gas API #30-0 39-05938

Property Name LYDIA RENTZ Well No. 4 Location: Unit A Section 19 Township 25N Range 03W

Well Status (Producing) Tubing 97 Intermediate N/A Casing 258 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	<u>0</u>		<u>258</u>			Steady Flow	
10 min	<u>0</u>		<u>258</u>			Surges	
15 min	<u>0</u>		<u>258</u>			Down to Nothing <u>XX</u>	
20 min						Nothing	
25 min						Gas <u>XX</u>	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

Oil Cons. Div
District III

JUL 20 2012

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS: Bradenhead pressure blew down to zero in 3 seconds.

By Bruce Martin
by April E. Pohl
(Position)

Witness _____

E-mail address _____