



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 7-22-10 Operator Chevron Midcontinent, L.P. API #30-0 39-21717

Property Name RINCON UNIT Well No. 79A Location: Unit D Section 17 Township 27N Range 06W

Well Status (Producing) Tubing 59 Intermediate 18 Casing 102 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
5 min	<u>0</u>	<u>18</u>	<u>102</u>	<u><1</u>	<u>102</u>
10 min	<u>0</u>	<u>18</u>	<u>102</u>	<u><1</u>	<u>102</u>
15 min	<u>0</u>	<u>18</u>	<u>102</u>	<u><1</u>	<u>102</u>
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		<u>XX</u>
Surges		
Down to Nothing		
Nothing	<u>XX</u>	
Gas		<u>XX</u>
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

Oil Cons. Div
District III

JUL 20 2012

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 10

REMARKS:

By Bruce Martin
by April E. Pohl
(Position)

Witness _____

E-mail address _____