



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 7-23-10 Operator Chevron Midcontinent, L.P. API #30-0 39-06989

Property Name RINCON UNIT Well No. 108 Location: Unit G Section 19 Township 27N Range 06W

Well Status (Producing) Tubing 49 Intermediate N/A Casing 53 Bradenhead \*

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS  
BRADENHEAD INTERMEDIATE

Steady Flow \_\_\_\_\_

Surges \_\_\_\_\_

Down to Nothing \_\_\_\_\_

Nothing \_\_\_\_\_

Gas \_\_\_\_\_

Gas & Water \_\_\_\_\_

Water \_\_\_\_\_

**DENIED**

BY: Brandon Powell  
DATE: 7/10/12 (505) 334-6178

Test required by  
11/12/12

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

Oil Cons. Div  
District III

JUL 20 2012

5 MINUTE SHUT-IN PRESSURE BRADENHEAD \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS: BH Valve was frozen in open position. I could not close it.

By Bruce Martin  
by April E Pohl  
Position \_\_\_\_\_

Witness \_\_\_\_\_

E-mail address \_\_\_\_\_