



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 7-16-10 Operator Chevron Midcontinent, L.P. API #30-0 39-24688

Property Name RINCON UNIT Well No. 276 Location: Unit A Section 13 Township 27N Range 07W

Well Status (Producing) Tubing 38 Intermediate N/A Casing 41 Bradenhead *

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow _____

Surges _____

Down to Nothin _____

Nothing _____

Gas _____

Gas & Water _____

Water _____

DENIED

BY: Brandon Powell
DATE: 7/10/12 (505) 334-6178

test required by 11/2/12

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

Oil Cons. Div
District III

JUL 20 2012

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS: The Bradenhead valve was open when I arrived and I could not close it. I did not want to break off the stem.

By Bruce Martin
by April E Pohl
(Position)

Witness _____

E-mail address _____