



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-29-12 Operator Kro Energy API #30-0 45-33375
Property Name Porcotee FC 15 Well No. 17 Location: Unit 0 Section 15 Township 29 Range 12
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 44 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>45</u>		
10 min	<u>0</u>		<u>46</u>		
15 min	<u>0</u>		<u>47</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	<u>DIST. 3</u>
Surges	
Down to Nothing	<u>OIL CONS. DIV.</u>
Nothing	<u>RCVD AUG 29 '12</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

H₂S test performed - Nothing when opened -
No H₂S detected.

By Dale Simmon

Witness

Monica Kuehling

LEASE OPERATOR

(Position)

E-mail address _____