

District I
1625 N. French Dr , Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15 29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP America Production Company	Contact: Courtney Cochran	
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457	
Facility Name: Howell 1A	Facility Type: Natural Gas Well	
Surface Owner: Federal	Mineral Owner: Federal	API No.: 300452224800

LOCATION OF RELEASE

Unit Letter I	Section 20	Township 30N	Range 08W	Feet from the 1850	North/South Line South	Feet from the 1105	East/West Line East	County: San Juan
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 36.79463 Longitude 107.69403

NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release: 111.5 MCF	Volume Recovered: none
Source of Release: fuel pot on compressor	Date and Hour of Occurrence: 8/25 5am - 8/26 7am	Date and Hour of Discovery: 8/26 7 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? RCVD SEP 13 '12 OIL CONS. DIV.	
By Whom?	Date and Hour DIST. 3	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

1/4 inch nipple broke off 8 inch fuel pot that feeds pressure to the scrubber dump on the suction scrubber. Well is shut-in and awaiting repairs.

Describe Area Affected and Cleanup Action Taken.*

Natural Gas dissipated to atmosphere so no clean-up action possible.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by Environmental Specialist: 	
Title: Environmental Advisor	Approval Date: 10/23/2012	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/6/2012	Phone: 505-326-9457	

* Attach Additional Sheets If Necessary

n5K1229739831