



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

RCVD NOV 1 '12
OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11-1-12 Operator Devon (SWD) API #30-0 45-21341

Property Name Northeast Blanco Unit Well No. 1 Location: Unit G Section 32 Township 31 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 1176 Intermediate 3 Casing -2 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	3	-2	0	-2
10 min	0	3	-2	0	-2
15 min	0	3	-2	0	-2
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD -2 INTERMEDIATE 0

REMARKS:

nothing on Bradenhead. Intermediate blew down to nothing
in 2 min.

By Phil J.
LEAD OPERATOR TECH
(Position)

Witness Paul White

E-mail address _____