

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

**NOV 01 2012**

Date of Test 6-11-12 Operator Dugan Production Corp. API # 30-045-25515  
Property Name HERRY MONSTER Well No 1 Location: Unit M Section 12 Township 24N Range 11W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 10 Intermediate 0 Casing 20 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

**PRESSURE**

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0	0	20	0	20	
10 minutes	0	0	20	0	20	
15 minutes	0	0	20	0	20	
20 minutes	0	0	20	0	20	
25 minutes	0	0	20	0	20	
30 minutes	0	0	20	0	20	

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

**FLOW CHARACTERISTICS**

BRADENHEAD	INTERMEDIATE
✓	✓

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

By Clay E. Davis  
Switcher  
(Position)

Witness \_\_\_\_\_