

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

**NOV 01 2012**

Date of Test 5/23/12 Operator Dugan Production Corp. API # 30-045-26822  
Property Name GOLD MEDAL Well No 3 Location: Unit I Section 31 Township 24N Range 10W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 50 Intermediate N/A Casing 50 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

**PRESSURE**

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	<u>2</u>		<u>50</u>			
10 minutes	<u>2</u>		<u>50</u>			
15 minutes	<u>2</u>		<u>50</u>			
20 minutes	<u>2</u>		<u>50</u>			
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

**FLOW CHARACTERISTICS**

BRADENHEAD	INTERMEDIATE
<u>✓</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 2 INTERMEDIATE \_\_\_\_\_

REMARKS:

By

W/98  
Switcher  
(Position)

Witness \_\_\_\_\_