NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 0 1 2012

Date of Test	5-22	-12	Opera	tor	Dugan Production Corp.				API# 30-045-30094					_	
Property Name	HERI	MIT AC	SE CO	OM	Well No	90	Location	: Unit	L	Section	_33_	Township	_26N	Range	12W
Well Status(Sh	ut-In or Pro	ducing)	Initia	I PSI:	Tubing		Intermed	liate		_Casing	<u>, 5</u>		_Bradenl	h <u>ead</u>	<u></u>
OPEN BRAI	ı	PRESSI	JRE		DIATE	ТО АТМО	OSPHERI	E INDIV					EACH		
	Bradenhead Interm								FLOW CHARACTERISTICS						
TIME	BH Int.	1	Int	Csg	I				BRADI	ENHEAD		INTERME	DIATE	-	
5 mintues	 	5				Steady Flo	w							-	
10 minutes	0	5				Surges								_	
15 minutes	0	5				Down to No	othing							_	
20 minutes	0	5				Nothing		(9						
25 minutes	0	5				Gas						,		_	
30 minutes	0	5				Gas & Wat	or ·		 -	·			,	_	
30 minutes	L- <u>-</u>	<u> </u>			ļ	Water	.01					,		-	
•						Water								-	
<u>If bradenh</u>	ead flow	∕ed w	ater,	chec	k all c	of the de	scriptio	ns tha	t appl	y belov	<u>v:</u>				
						•									•
	•	CLEAR			FRÈSH		_SALTY		SULFU	IR	BLACK	<u> </u>	_		
5 MINUTE S	SHUT-IN		BRAD	ENHEA	\D	Ö	_	INTER	MEDIATE	Ξ					
REMARKS:						·									
<u></u> .										•				-	
														-	
										· · · · · · · · · · · · · · · · · · ·				_	
<u>. </u>							·			_				-	
				c											
Ву		200	T7 \$	mes of the second				Witness	s					_	
			Swite				_								
			(Positi	on)											