

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 01 2012

Date of Test 6-11-12 Operator Dugan Production Corp. API # 30-045-33217
Property Name HERRY MONSTER SWD Well No 3 Location: Unit F Section 11 Township 24N Range 11W
Well Status(Shut-In or Producing) Initial PSI: Tubing 10 Intermediate NA Casing 2 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0	NA	0	NA	0	
10 minutes	0	NA	0	NA	0	
15 minutes	0	NA	0	NA	0	
20 minutes	0	NA	0	NA	0	
25 minutes	0	NA	0	NA	0	
30 minutes	0	NA	0	NA	0	

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
✓	✓

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

REMARKS:

By

Play Elken
Switcher
(Position)

Witness