

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX (505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 01 2012

Date of Test 6-27-12 Operator Dugan Production Corp. API # 30-045-25123
Property Name JULY JUBILEE Well No 2 Location: Unit D Section 29 Township 24N Range 9W
Well Status(Shut-In or Producing) Initial PSI: Tubing 30 Intermediate Casing 20 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		20			
10 minutes	0		20			
15 minutes	0		20			
20 minutes	0		20			
25 minutes	0		20			
30 minutes	0		20			

FLOW CHARACTERISTICS

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

BRADENHEAD	INTERMEDIATE
<u>Nothing</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

REMARKS:

By

Luis Vasquez

Witness

Switcher

(Position)