

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

**NOV 01 2012**

Date of Test 5-16-12 Operator Dugan Production Corp. API # 30-045-25711  
Property Name HUGH LAKE Well No 2 Location: Unit A Section 29 Township 27N Range 12W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate      Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

**PRESSURE**

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		0			
10 minutes	0		0			
15 minutes	0		0			
20 minutes	0		0			
25 minutes	0		0			
30 minutes	0		0			

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

**FLOW CHARACTERISTICS**

BRADENHEAD	INTERMEDIATE
X	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR      FRESH      SALTY      SULFUR      BLACK     

**5 MINUTE SHUT-IN**

BRADENHEAD

0

INTERMEDIATE

REMARKS:

By

*David King*

Switcher

(Position)

Witness