NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

BRADENHEAD TEST REPORT (Submit 1 copy to above address)

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

OIL CONS. DIV DIST. 3

NOV 0 1 2012

											110 1	_	
Date of Test	5-23-11 Operator			tor	Dugan	on Corp.		API#	30-045-	-26530			
Property Name	·	IVY LE	AGUE	,	Well No	1	Location: Un	it	Α	_Section _	17 Township	24N Rang	je <u>9W</u>
Well Status (Sh	ut-In o	roducing)) Initia	ıl PSI:	Tubing	40	_Intermediate	na		_Casing _	30	Bradenhead	۵
ODEN DDA	ראוו ור	. V D V V II	T INIT		:רועדר	TO ATMO	SOULDE IN	ורטוג עור	N 1 A 1	! V EOD	15 MINUTES	EACH	
OPEN BRAI	DENHE	PRESS		-RIVIE	DIATE	TO ATMC	OSPHERE IN	וואוטו	JUAL	LYFUR	15 MINUTES	EACH	
	Bradenhead Interm						FLOW CH			HARACTERISTICS			
TIME		nt Csg	Int	Csg						ENHEAD	INTERME	DIATE	
5 mintues	0	30				Steady Flov				1			
			1		1		" <u> </u>			 			
10 minutes	0	30	 		1	Surges		<u>_</u>		1			
15 minutes	0	30			_	Down to No	othing						
20 minutes	 	30	 			Nothing		<u>×</u>					
25 minutes	0	30	.		1	Gas							
30 minutes		30				Gas & Wate	er						
						Water							
			•										
<u>If bradenh</u>	ead fl	owed v	vater,	che	ck all o	f the de	scriptions	that :	appl	y below	<u>:</u>		
										_			
		CLEAR	· —		FRESH		_SALTY	s	SULFU	R	BLACK	_	
5 MINUTE S	SHUT-II	N	BRAD	ENHE.	AD	×	IN ⁻	TERME	DIATE	=			
REMARKS:		-	5. (, ,5				_ "'						
			<u>-</u>										
	· · · · · · · · · · · · · · · · · · ·	<u> </u>			$\overline{}$								
	,	no 1)								
Ву	_//	D.K			2//		Wi	tness_					
			Swit (Posit				_						
			เกษา										