## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 0 1 2012

Date of Test	est <u>S 09-12</u> Operator					Producti	on Corp.		_API#	30-045-28804				-	
Property Name		JETI	ER	/_	Well No	4	Location:	Unit	A_	Section	1	Township	25N	Range	13W
Well Status(Sh	ut-In or	oducing)	Initia	al PSI	Tubing	_5	Intermed	iate 🖊	1 A	_Casing		<i>-</i>	Bradent	nead	. O_
OPËN BRAI		PRESS	URE		DIATE T	TO ATM	OSPHERI	E INDIV					EACH		
TIME	Bradenhead Interm  BH Int Csg Int Csg						FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE							•	
TIME 5 mintues	0	4	Int	Csg		Steady Flo	ow		BKADE	NHEAD		INTERME	DIATE	-	
10 minutes	0	4	<b> </b>		1	Surges								-	
15 minutes	0	4				Down to N	lothing							_	
20 minutes	0	4			(	Nothing								_	
25 minutes	0	4				Gas									
30 minutes	0	4				Gas & Wa	ter							-	
				<b>+</b>	-	Water		-						-	
If bradenhead flowed water, check all of the descriptions that apply below:  CLEARFRESHSALTYSULFURBLACK															
5 MINUTE S	NI-TUH		BRAD	)ENHE	AD .	O	_	INTER	MEDIATE		/A-				
													in the second	•	
									-					-	
	_			_								<u>:</u>		-	
Ву	Irav	15 2		•	n	38	_	Witness	s		_		<u></u>	-	
			Swit (Posit	cher		<del></del> ·	_								