## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 0 1 2012

											MOA A T SOIL					
Date of Test	<u>5-23-/2</u> Operator			Dugan Production Corp.				_API#	30-045-29191							
Property Name	GOODMAN					Well No.	2	Location:	Unit	L_	Section	23	Township	22N	Rang	e <u>08W</u>
Well Status(Sho	ùt-In c	it-In or Producing) Initial PSI:				Tubing	80	Intermed	Intermediate		_Casing .	150		_Bradenh <u>ead</u>		Ø
OPEN BRAI	DENI				ERME	DIATE	ГО АТМО	DSPHER	E INDIV	'IDUAL	LY FOR	15 M	INUTES	EACH		
PRESSURE  Bradenhead Interm									FLOW	CHARACT	TERIS	rics				
TIME	вн	Int	Csg	Int	Csg	_					NHEAD		INTERMEI	DIATE		
5 mintues	Ø		150				Steady Flo	w								
10 minutes	Ø		150				Surges								•	
15 minutes	Ø		150					1					•			
20 minutes -	K		150				Nothing								•	
25 minutes							Gas			•					•	
30 minutes							Gas & Wat	er							•	
		<del>''</del>			i	<b>-</b>	Water						•		•	
<u>If bradenh</u>	ead_	flow	<u>ed w</u>	ater	, che	ck all o	f the de	scriptio	ns tha	t appl	y below	<u>/:</u>			•	
		(	CLEAR			FRESH		SALTY		SULFU	R	BLAC	<			
5 MINUTE S	HUT						Ø	_		_				-		
REMARKS:						-		_					•			
	-															
Ву		<u>//</u>	M	i	<b>&gt;</b>	فحر		<u>-</u>	Witness	s			····			
•					cher			_			•					
				(Posit	IOH)											