

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

**JIL CONS. DIV DIST. 3**

**NOV 01 2012**

Date of Test 5-16-12 Operator Dugan Production Corp. API # 30-045-29829  
Property Name HUGH LAKE Well No 90 Location: Unit M Section 33 Township 27N Range 12W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 20 Intermediate            Casing 10 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH.	Int	Csg	Int	Csg	
5 minutes	0		10			
10 minutes	0		10			
15 minutes	0		10			
20 minutes	0		10			
25 minutes	0		10			
30 minutes	0		10			

FLOW CHARACTERISTICS

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

BRADENHEAD	INTERMEDIATE
X	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR            FRESH            SALTY            SULFUR            BLACK           

**5 MINUTE SHUT-IN**

BRADENHEAD

0

INTERMEDIATE

REMARKS:

By

Dugan, Tony

Witness

Switcher

(Position)