NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

OIL CONS. DIV DIST. 3

NOV 0 1 2012

					Dugan Production Corp.								
Property Name	ty NameLISBON			_Well No2 Location:			Unit	E	_Section	11 Township	30N_Rar	ige <u>14W</u>	
Well Status(Shut-In or Producing) Initial PSI:					Tubing	110	Intermed	iate <i>©</i>	•	_Casing	20	Bradenh <u>ead</u>	<u> </u>
OPEN BRAI		PRESS	URE		DIATE	ТО АТМ	OSPHERI	E INDIV			15 MINUTES	SEACH	
TIME	Bradenhead Interm BH Int Csg Int Csg							FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE				EDIATE	
TIME				,	Ī				BRADE	NHEAD	INTERM	EDIATE	
5 mintues		90	0	0	1	Steady Flo	ow						
10 minutes	<u>6</u>	20]	Surges							
15 minutes	0	20				Down to N	Nothing						
20 minutes	0 _	20				Mothing							
25 minutes	0	20				Gas							
30 minutes	0	10			1	Gas & Wa	ater		······································				
oo mindes				Water									
						,,,,,,							
lf bradenh	ead flov	ved w	ater,	che	ck all	of the de	escriptio	ns that	t apply	y below	<u>/:</u>		
		CLEAR			FRESH		SALTY		SULFU	R	BLACK		
5 MINUTE S	SHUT-IN		BRAD	ENHE	ΑD		···	INTERM	//EDIATE	=			
REMARKS:													
											<u> </u>	,	
												·	
					,								•
					,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		•••				.		
By	Ha	ار بربر	(MA	22	•		Witness	,,				
_ ,		- 	Swit		<u> </u>	and the same of th							
			(Positi										