NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division

Aztec District Office

1000 Rio Brazos Road

Aztec, NM 87410

(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District.III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 0 1 2012

Date of Test	6-22-12	Operator	Dugan Production Corp.			# <u>30-045</u>	30-045-32257			
Property Name	LISBO	ON	Well No	3 Location:	: Unit N	Section	11 Township			
Well Status(Shut-In or Producing) Initial PSI:			Tubing <u>85</u> Intermedi		iate 🖒	Casing	24.	Bradenhead 🔨		
OPEN BRAI	DENHEAD AND PRESSI		DIATE TO A	TMOSPHER	E INDIVIDUA	ALLY FOR	15 MINUTES	EACH		
	Bradenhead Interm						FLOW CHARACTERISTICS			
TIME	BH Int Csg	Int Csg			BRA	DENHEAD	INTERME	DIATE '		
5 mintues	0024	00	Stead	y Flow						
10 minutes	0 24		Surge	s						
15 minutes	0 24		Down	to Nothing						
20 minutes	0 24		Nothir	វិទ្ធ						
25 minutes	0 24		Gas							
30 m̃ınutes	0 24			. Water	And an order					
	<u> </u>		Water							
							· · · · · · · · · · · · · · · · · · ·	•		
<u>lf bradenh</u>	ead flowed w	ater, chec	k all of the	descriptio	ns that ap	ply belov	<u>v:</u>			
	CLEAR		FRESH	SALTY	SUL	FUR	BLACK	_		
5 MINUTE S	SHUT-IN	BRADENHEA	.D. >	3	INTERMEDIA	ATF				
REMARKS:										
								· · · · · ·		
										
						•		.		
Ву	Harry	Small	ムモ		Witness					
By Harry Sme Switcher			ALTERNA AND STATES							
		(Position)		 						