## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division

Aztec District Office

1000 Rio Brazos Road

Aztec, NM 87410

(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 0 1 2012

Date of Test $\sqrt{\frac{7}{23}/12}$ Operator					ator	Dugan Production Corp. API# 30-045-33724								
Property Name	IRISH (			ОМ		_Well No5	Location	n: Unit	M	Section	11 Township		_26N_Rar	nge <u>13W</u>
Well Status(Shut-In or Producing) Initial PSI:					al PSI:	Tubing <u>27</u>	Intermed	diate 1	<u>// 4</u>	_Casing	_27		_Bradenh <u>ead</u>	
OPEN BRA	DENI		O ANE		ERME	EDIATE TO ATM	OSPHER	RE INDIV	'IDUAL	LY FOR	: 15 MIN	IUTES	EACH	
Bradenhéad Inter				Intern	n				FLOW CHARACTERISTICS					
TIME	ВН	Int	Csg	Int	Csg	7			BRADE	ENHEAD	11	NTERME	DIATE	
5 mintues	0		27			Steady Flo	ow						· 	
10 minutes	0		27			Surges								
15 minutes	0		27			Down to N	Vothing							
20 minutes	0		27			Nothing	)							
25 minutes	:					Gas	•							
30 minutes	ζ.					Gas & Wa	ater						<del>-</del>	
	<u> </u>	+		1	-	⊒ Water								
				•						,			·	
<u>lf bradenh</u>	ead	flow	red w	ater	<u>, che</u>	ck all of the de	<u>escriptic</u>	ons tha	t appl	y belov	<u>v:</u>			•
													•	
		(	CLEAR			_FRESH	SALTY		SULFU	IR	BLACK_		_	
5 MINUTE S	HUT	-IN		BRAI	DENHE	ad <u>()</u>	_	INTERN	MEDIATE	= <i>N</i> ,	/A		,	
REMARKS:	-1 2,	Ar	o <u>l</u>											
	7	i	\	-										
								<del></del>	<del></del>					
								··········					<del></del>	
<del></del>														
Ву		h						Witness	s					
				Swi	tcher									
				(Posi	tion)									