& NATURAL RESOURCES DEPARTMENT Aztec District Office 1000 Rio Brazos Road Aztec, NM 87410 (505)334-6178 FAX:(505)334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm **BRADENHEAD TEST REPORT** OIL CONS. DIV DIST. 3 (Submit 1 copy to above address) NOV 0 1 2012 Dugan Production Corp. API # 30-045-33824 Date of Test 5-16-12 Operator Property Name HUGH LAKE Well No. 91S Location: Unit H Section 33 Township 27N Range 12W Well Status(Shut-In or Roducing) Initial PSI: Tubing /O Intermediate Casing /O OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH **PRESSURE FLOW CHARACTERISTICS** Bradenhead Interm Int Csg TIME ВН Int Csg **BRADENHEAD** INTERMEDIATE 10 Steady Flow 5 mintues 0 10 minutes Surges 10 0 Down to Nothing 15 minutes 0 10 20 minutes Nothing 10. 25 minutes Gas 0 10 30 minutes Gas & Water Water If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK \circ **5 MINUTE SHUT-IN** BRADENHEAD INTERMEDIATE REMARKS: By Switcher

(Position)

NEW MEXICO ENERGY, MINERALS

Oil Conservation Division