NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

ESOURCES DEPARTMENT

BRADENHEAD TEST REPORT

Aztec District Office 1000 Rio Brazos Road Aztec, NM 87410 (505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

Oil Conservation Division

(Submit 4 approximate above address)

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

Date of Test					Dugan Production Corp.						-					
Property Name	ne GOLD MEDAL				Well No	92S	Location	: Unit	D	_Section	33Td	33 Township				
Well Status(Shu	ut-In or Proc	ducing)	Initia	ıl PSI:	Tubing	<u>65</u>	Intermed	iate C	<u> </u>	_Casing	20)	_Bradent	nead C	<u>) </u>	
OPEN BRAC		PRESSI			DIATE	TO ATMO	OSPHERI	E INDIV			R 15 MIN		EACH			
TIME	BH Int	Csg	Int	Csg					BRADE	NHEAD	IN	TERME	DIATE	_		
5 mintues	0			20		Steady Flo	w									
10 minutes	0			20		Surges								•		
15 minutes	0			20		Down to No	othing						·	•		
20 minutes						Nothing			~					· _		
25 minutes						Gas								_		
30 minutes						Gas & Wat	er							_		
·					Water									-		
If bradenho	ead flow	<u>ed w</u>	ater,	chec	k all c	of the de	scriptio	ns that	t appl	y belov	<u>w:</u>					
	C	CLEAR			FRESH		_SALTY		SULFU	R	BLACK_		_			
5 MINUTE S REMARKS:	HUT-IN		BRAD	ENHEA	D	O	_	INTERM	MEDIATE							
														-		
														_		
Ву	12/21	INY	S	CHA	NE 15			Witness	s					-		
			Swite (Positi				_									