

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 01 2012

Date of Test 6-22-12 Operator Dugan Production Corp. API # 30-045-23847
Property Name DOMA NAVAJO 21-27-13 Well No. 3 Location: Unit M Section 21 Township 27N Range 13W
Well Status(Shut-In or Producing) Initial PSI. Tubing 5 Intermediate _____ Casing 20 Bradenhead 20

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	<u>20</u>		<u>20</u>			
10 minutes	<u>20</u>		<u>20</u>			
15 minutes	<u>20</u>		<u>20</u>			
20 minutes	<u>20</u>		<u>20</u>			
25 minutes	<u>20</u>		<u>20</u>			
30 minutes	<u>20</u>		<u>20</u>			

FLOW CHARACTERISTICS

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water

BRADENHEAD	INTERMEDIATE
<u>X</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 20 INTERMEDIATE _____

REMARKS

By [Signature]
Switcher
(Position)

Witness _____