

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

**NOV 01 2012**

Date of Test 5-22-12 Operator Dugan Production Corp. API # 30-045-24905  
Property Name ELWOOD P DOWD Well No 2 Location: Unit P Section 10 Township 24N Range 09W  
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

**PRESSURE**

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		0			
10 minutes	0		0			
15 minutes	0		0			
20 minutes	0		0			
25 minutes	0		0			
30 minutes	0		0			

**FLOW CHARACTERISTICS**

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

BRADENHEAD	INTERMEDIATE
X	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD

X

INTERMEDIATE

REMARKS:

hole in tubing

By

Mike Sneed

Witness

Switcher

(Position)