NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
.(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV A 1 2012

Date of Test	6-2	7-12	Opera	ator	Dugan	Producti	on Corn		ΔPI #	NUV U 1 ZUIZ 30-045-26405				
									_	,			0411	- 4014
Property Name	_	_								_				
Well Status(St	nut-In o	Producing)) Initi	al PSI:	Tubing _	150	Intermedia	ate		_Casing	<u> 351)</u>		_Bradenh	ead 🔵
	-							<u></u>						
OPEN BRA	DENH	IEAD AN	D INT	ERME	DIATE 1	O ATM	OSPHERE	INDIV	IDUALI	LY FOR	t 15 MINU	JTES I	EACH	
		PRES	SURE											
Bradenhead Interm						•		FLOW CHARACTERISTICS						
TIME	ВН	Int Csg	Int	Csg	-		-		BRADE	NHEAD	INT	rermei	DIATE	
5 mintues	8	350] ;	Steady Flo	ow .							
10 minutes	0	356				Surges								
15 minutes	0	350				Down to N	othing					, ,		
20 minutes	D	350				Nothing	•						_	
25 minutes	0	350				Gas	·							
30 minutes	0	350	,] ,	Gas & Wat	ter							
				+	_	Water	•				-			
							-							
<u>If bradent</u>	ead 1	flowed v	<u>water</u>	, che	ck all of	f the de	scription	s that	apply	/ belov	<u>v:</u>			
		CLEA	₹		FRESH -		SALTY -		SULFU	R	BLACK		-	
5 MINUTE :	SHUT	-iN	BRAI	DENHE.	ΔD	7		INTERM	1EDIATE					
REMARKS.			2,	<i>></i>	-	<u> </u>				- -				
·														
		•	_											
					18.181		 						<u> </u>	
Ву	R.	res-	JL.		7			Witness						
- •	المركب		Swi	tcher			_						 	
			(Posi				_							