NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT,

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 0 1 2012

													,,,	J. J		
Date of Test	4	()]	2_	Opera	tor	Dugan	Product	tion Corp		_API#	30-04	5-268	21		_	
Property Name	·	C.	ALG/	ARY		Well No	2	Locatio	n: Unit	G	Section	6	Township	23N	Range	10W.
Well Status(Sh	ut-In oƘ	Prodi	ucing)	Initia	I PSI:	Tubing	40	Interme	ediate 🔨	JA_	_ Casing	40		Braden	nead 🛶	7
ÒPEN BRA	DENII		ANID	INITE	- D. A.È		TO ATM	IOCDUE	>= INIDI\	(IDLIAI	LVEOF) 4E N	AINILITEO			
OPEN BRA	DENH		RESSI		ERIVIE	DIATE	IOAIN	IOSPHEI	אב וועטוי	VIDUAL	LYFOR	K ID IV	IIINO I ES	EACH		
Bradenhead				Interm						FLOW CHARACTERISTICS			TICS			
TÍME		Int		Int	Csg						ENHEAD		INTERME	DIATE		
5 mintues	0		40				Steady FI	low							-	
10 minutes	0	$\neg \neg$	40			1	Surges								-	-
15 minutes		_	45			Down to Nothing			***						=	
	0		40			Ī					<u></u>	+			-	
20 minutes		- 10			Nothing				<u> </u>					-		
25 minutes		_+				1	Gas								-	
30 minutes							Gas & Wa	ater							_	
							Water								-	
lf bradent	oad f	low	w he	ater	che	ck all d	of the d	ascrinti	one the	at anni	v helov	A/*				
II DI GGCIII	icau i	10,11	<u> </u>	ator,	OHIC	on an c	or the u	COCIDE	OHS CHE	at appi	y belo					
		С	LEAR			FRESH		SALTY	,	_SULFU	JR	BLAC	κ	_		
							ml									
5 MINUTE S	SHUT-	IN		BRAD	ENHE	AD			INTER	MEDIATI	E		-			
REMARKS:																
															-	
															-	
		-											•		-	
												,			-	
				. 10	38											
Ву				lak"	10				Witnes	ss					-	
		•		SWit	cher											

(Position)

