

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3distnc.htm](http://emnrd.state.nm.us/ocd/District%20III/3distnc.htm)

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 01 2012

Date of Test 6-20-12 Operator Dugan Production Corp. API # 30-045-29239
Property Name BUDDHA TEMPLE Well No 90 Location: Unit A Section 30 Township 24N Range 8W
Well Status(Shut-In or Producing) Initial PSI: Tubing 52 Intermediate Casing 45 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		45			
10 minutes	0		45			
15 minutes	0		45			
20 minutes	0		45			
25 minutes	0		45			
30 minutes	0		45			

FLOW CHARACTERISTICS

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

BRADENHEAD	INTERMEDIATE
X	

If bradenhead flowed water, check all of the descriptions that apply below: NONE

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

By

Rocky Olson 97

Switcher

(Position)

Witness