

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

**NOV 01 2012**

Date of Test 6/23/12 Operator Dugan Production Corp. API # 30-045-29986  
Property Name COM Well No 4 Location: Unit C Section 2 Township 29N Range 14W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 25 Intermediate NA Casing 10 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

**PRESSURE**

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		10			
10 minutes	0		10			
15 minutes	0		10			
20 minutes	0		10			
25 minutes	0		10			
30 minutes	0		10			

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

**FLOW CHARACTERISTICS**

**BRADENHEAD**

**INTERMEDIATE**

✓	

If bradenhead flowed water, check all of the descriptions that apply below: None

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD 0

INTERMEDIATE \_\_\_\_\_

REMARKS:

---



---



---



---

By Brian Vernal  
Switcher  
(Position)

Witness \_\_\_\_\_