

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

**NOV 01 2012**

Date of Test 7-10-12 Operator Dugan Production Corp. API # 30-045-34220  
Property Name CHAMP Well No 91 Location: Unit N Section 5 Township 23N Range 10W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 70 Intermediate 0 Casing 22 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm	
	BH	Int	Csg	Int	Csg
5 minutes	0				22
10 minutes	0				22
15 minutes	0				22
20 minutes					
25 minutes					
30 minutes					

FLOW CHARACTERISTICS

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

BRADENHEAD

INTERMEDIATE

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

By Kenny Schale  
Switcher  
(Position)

Witness \_\_\_\_\_