NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division Aztec District Office 1000 Rio Brazos Road Aztec, NM 87410 (505)334-6178 FAX (505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

QIL CONS. DIV DIST. 3

	ı				NOV 0 1 2012			
Date of Test	6 2112 Operat	tor <u>Dugan Production</u>	Corp.	_API#	30-045-0	5811		
Property Name	WEST BISTI UN	IT Well No 104	Location: Unit	N	_Section	18 Township	26N Range	13W
Well Status(Sh	nut-In of Producing) Initia	I PSI: Tubing \\ \rightarrow 0	Intermediate //	10	_Casing _	10	Bradenhead .	. U
OPĖN BRA	PREŜSURE	ERMEDIATE TO ATMOS	SPHERE INDIV		LY FOR 1		EACH	
TIME		Csg 4			ENHEAD	INTERME	DIATE	
5 mintues	0 1/0	Steady Flow			. [
10 minutes	α_{ll}							
	0110	Surges				· =#•		
15 minutes	O UN	Down to Noth	<u></u>					
20 minutes	9 110	Nothing						
25 minutes	01/10	Gas						
30 minutes	1,60	Gas & Water	· 			· <u>-</u>		
		Water						
<u>If bradent</u>	nead flowed water,	check all of the des	criptions tha	t appl	y below:			
					•			
	CLEAR	FRESH	SALTY	SULFU	IRBL	ACK	_	
5 MINUTE	SHUT-IN BRADI	ENHEAD	. INTERN	MEDIATE	<u> </u>	<u>. </u>		
REMARKS:								
	<u>. </u>					-	<u>. </u>	
·		- 100 100 100					•	
•							<u> </u>	
		1777						
Ву	Aldo	Doxaco	Witness	s	<u></u>			
	Swite							
	(Position	on)						