## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division Aztec District Office 1000 Rio Brazos Road Aztec, NM 87410 (505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

	6-20-11	Dugan Production Corp. API#			NOV 0 1 2012					
	_						_			01
	_				Location: Unit				-	
Well Status(Sh	ut-In or Producing	)_ Initial PSI:	Tubing _	65	Intermedia <u>te</u>		_ Casing .	6 ~	_Bradenh <u>ead</u>	<u>0.</u>
OPEN BRAI	DENHEAD AN	D INTERME	EDIATE T	ГО АТМО	OSPHERE IND	IVIDUAL	LY FOR	15 MINUTES I	EACH <sup>`</sup>	
	PRESS	SURE								
	Bradenhead	Interm		,		FLOW	CHARACT	TERISTICS		
TIME	BH Int Csg	Int Csg	7			BRADI	ENHEAD .	INTERME	DIATE	
5 mintues	0 62		] :	Steady Flo	w					
10 minutes	0 62		] :	Surges						
15 minutes	0 62			Down to No	othing					
20 minutes	0 62			Nothing		X			<u> </u>	
25 minutes	0 62			Gas						
30 minutes	0 62	<u> </u>	] ,	Gas & Wat	ter					
	•	•	,	Water					_	
<u>lf bradenh</u>	ead flowed v	vater, che	ck all o	f the de	escriptions th	at appl	y below	! NOWE		
	CLEAF	₹	FRESH _		SALTY	SULFU	IR	BLACK	_	
5 MINUTE S	SHUT-IN	BRADENHE.	AD _	<u>6</u>	INTE	RMEDIATE				
					- 4					
<u>~</u>			<del></del>	<del></del>					<del></del>	
Ву	<u>Dean</u>	~ /	1 q	7	Witne	ess				
		Switchér (Position)			_					