

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX: (505)334-6170

[http://emr.state.nm.us/ocd/District III/3district.htm](http://emr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

**NOV 01 2012**

Date of Test 9-20-12 Operator Dugan Production Corp. API # 30-045-25431  
Property Name TURKS TOAST Well No 2 Location: Unit D Section 19 Township 30N Range 14W  
Well Status (Shut-In or Producing) Initial PSI: Tubing 200 Intermediate        Casing 300 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

**PRESSURE**

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	<u>0</u>		<u>300</u>			
10 minutes	<u>0</u>		<u>300</u>			
15 minutes	<u>0</u>		<u>300</u>			
20 minutes	<u>0</u>		<u>300</u>			
25 minutes	<u>0</u>		<u>300</u>			
30 minutes	<u>0</u>		<u>300</u>			

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

**FLOW CHARACTERISTICS**

BRADENHEAD	INTERMEDIATE

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR 0 FRESH 0 SALTY 0 SULFUR 0 BLACK 0


**5 MINUTE SHUT-IN**

BRADENHEAD 0

INTERMEDIATE       

REMARKS:

By



Switcher

(Position)

Witness