

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

**NOV 01 2012**

Date of Test 10/12/12 Operator Dugan Production Corp. API # 30-045-26497  
Property Name MARY LOU Well No. 2 Location: Unit G Section 32 Township 24N Range 10W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 30 Intermediate NA Casing 30 Bradenhead A

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

**PRESSURE**

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	<u>A</u>		<u>30</u>			
10 minutes	<u>A</u>		<u>30</u>			
15 minutes	<u>A</u>		<u>30</u>			
20 minutes	<u>A</u>		<u>30</u>			
25 minutes						
30 minutes						

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

**FLOW CHARACTERISTICS**

BRADENHEAD	INTERMEDIATE

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD A INTERMEDIATE \_\_\_\_\_

REMARKS:

By

WJ 98  
Switcher  
(Position)

Witness \_\_\_\_\_