

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 01 2012

Date of Test 10/12/12 Operator Dugan Production Corp. API # 30-045-26776
Property Name MARY LOU Well No 4 Location: Unit O Section 32 Township 24N Range 10W
Well Status(Shut-In or Producing) Initial PSI: Tubing Ø Intermediate N/A Casing Ø Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm	
	BH	Int	Csg	Int	Csg
5 minutes	Ø		Ø		
10 minutes	Ø		Ø		
15 minutes	Ø		Ø		
20 minutes	Ø		Ø		
25 minutes					
30 minutes					

FLOW CHARACTERISTICS

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

BRADENHEAD	INTERMEDIATE
✓	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

Ø

INTERMEDIATE _____

REMARKS:

By

498

Switcher

(Position)

Witness _____