NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 0 1 2012

							110		
Date of Test.	.6/15/12	Operator	Dugan Productio	n Corp.	_API#	30-045	-29875		
Property Nam	e PAUL RE	VERE	Well No 94	_Location: Unit	A	Section	23 Township	26N Rang	je <u>13W</u>
Well Status(S	hut-In of (Producing)	Initial PSI:	Tubing 7.0	Intermediate //	ļa_	Casing	4;	Bradenhead	<u> </u>
OPEN BRA	AĎENHEÄD ANI PRESS		EDIATE TO ATMO	SPHERE INDIV	/IDUALI	LY FOR	15 MINUTES	EACH	
Bra'denhead Interm		FLOW CHARACTERIST				TERISTICS			
TIME	BH Int Csg	Int Csg	-	·	BRADE	NHEAD	INTERME	DIATE	
5 mintues	0 4		Steady Flow	<i>I</i>					•
10 minutes	0. 4		Surges						
15 minutes	0 4		Down to Not	thing		ļ			
20 minutes	6 4		Nothing						
	0 4								
25 minutes			Gas		_				
30 minutes	0 4	<u> </u>	Gas & Wate	·r				···	
			Water				-	<u> </u>	•
<u>If bradenl</u>	head flowed w	vater, che	ck all of the des	scriptions tha	t apply	/ below	<u>':</u>		
			-						
	CLEAR		FRESH	_SALTY	_SULFU	R	BLACK	- ,	
5 MINÚTÉ REMARKS:	SHUT-ÏN	BRADENHE	ad <u>()</u>	_ INTERI	MEDIATE	A N	(
			_						
		-							
					<u> </u>				
		<u>-</u>							
*									
Ву	Aldo	Daxo	1 (a	_ Witnes	s	``			
	,	Switcher							•
		(Position)		-					