

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX: (505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 01 2012

Date of Test 7-12-12 Operator Dugan Production Corp. API # 30-045-31696
Property Name MARY LOU Well No. 91S Location: Unit F Section 32 Township 24N Range 10W
Well Status(Shut-In or Producing) Initial PSI: Tubing 30 Intermediate 0 Casing 19 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0				19	
10 minutes	0				19	
15 minutes	0				19	
20 minutes						
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

BRADENHEAD

INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD 0

INTERMEDIATE _____

REMARKS.

By

Kenny Schaefer

Witness _____

Switcher

(Position)