

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/Districts/District%20III/3rdistrict.htm>

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

**NOV 01 2012**

Date of Test 6/6/12 Operator Dugan Production Corp. API # 30-045-31976  
Property Name PAUL REVERE Well No 93S Location: Unit F Section 22 Township 26N Range 13W  
Well Status (Shut-In or Producing) Initial PSI: Tubing 70 Intermediate N/A Casing 9 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

**PRESSURE**

TIME	Bradenhead			Interm	
	BH	Int	Csg	Int	Csg
5 minutes	0		9		
10 minutes	0		9		
15 minutes	0		9		
20 minutes	0		9		
25 minutes	0		9		
30 minutes	0		9		

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

**FLOW CHARACTERISTICS**

**BRADENHEAD**

**INTERMEDIATE**

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD

0

INTERMEDIATE

N/A

REMARKS:

By

Aldo Daxara  
Switcher  
(Position)

Witness

\_\_\_\_\_